

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

## 75 Hawthorne Street San Francisco, Ca. 94105

DEC 11 1991 In Reply Refer To: H-2-1 Site: NAV-010

Certified Mail: P 470 095 778

Raymond Barton Navajo Transportation Motor Pool P.O. Box 608 Navajo Nation Window Rock, AZ 86515

Dear Mr. Barton:

EPA is in receipt of additional information regarding the underground storage tank (UST) removals and installation at the Navajo Nation Motor Pool. EPA requested an UST notification form be submitted for the new USTs installed at the site in a March 15, 1991 letter, in addition to information on the final disposal of the old USTs which were removed.

EPA has received the UST notification form for the newly installed tanks and details on the proper disposal of the old USTs which were removed. This site does not appear to currently pose a threat to human health and the environment. EPA is not requesting any further action at this time.

Any additional response regarding this case should be submitted within 30 days of the receipt of this letter. If you have any questions, please contact Matthew Small, the Native American Lands Project Officer, at 415-744-2081.

Sincerely,

Patricia D. Eklund, Chief

Office of Underground

Storage Tanks

cc: Ed Dunn, US EPA Arizona
Sadie Hoskie, Navajo EPA
Audrey Benally, Navajo EPA
Rose Dewyenie, Bureau of Indian Affairs
Chuck Dowell, Indian Health Services



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street San Francisco, Ca. 94105

15 MAR 1991

In Reply Refer To: H-2-1 Certified Mail: P 735 586 825

Raymond Barton
Fleet Transportation
Navajo Tribal Motor Pool
P.O. Box 608
Navajo Nation
Window Rock, AZ 86515

Dear Mr. Barton:

This correspondence is in regard to a recent file review of information available on the underground storage tank (UST) removal and installation at the Navajo Tribal Motor Pool, Window Rock, Arizona.

The manner in which the site assessment report prepared by Rocky Mountain Petroleum dated June 6, 1990 is presented makes interpretation of the work performed very difficult. A more thorough presentation using gramatical descriptions of the step by step process of the tank removal and sampling would expedite the review process.

We are requesting an UST notification form (included) be submitted for the new UST's installed per 40 CFR § 280.22. In addition, the site assessment report was found to lack information on the final disposal of the removed tanks. Please provide this information.

After reviewing information in the site assessment report, it appears the levels of contamination are very low. The highest reported concentration was 13 ppm of total petroleum hydrocarbons. This site does not appear to pose a threat to human health and the environment.

The completed notification form and any additional response presented to the EPA regarding this case should be submitted within 60 days of the date of this letter. We appreciate your cooperation in this manner. If you have any questions, please contact Patrick Hogan, the Native American Lands Project Officer, at 414-744-2077.

SincereTy,

Patricia D. Eklund, Chief Office of Underground

Storage Tanks

cc: Ed Dunn, US EPA Arizona Louise Linkin, Navajo EPA

Audrey Benally, Navajo EPA

Rose Dewyenie; Bureau of Indian Affairs

Chuck Dowell, Indian Health Affairs

Enclosure

Ed Dunn 1243 West Carla Vista Drive Chandler, AZ 85224

(602) 963-8291

Louise Linkin Navajo EPA P.O. Box 308 Window Rock, AZ 86515 Navajo Nation

(602) 871-4941

Audrey Benally Navajo EPA P.O. Box 308 Window Rock, AZ 86515 Navajo Nation

(602) 871-4941

Rose Dewyenie
Bureau of Indian Affairs
Navajo Area Office
Environmental Quality Services
P.O. Box 1060, Code 305
Gallup, NM 87301

(602) 863-9501

Chuck Dowell Indian Health Services Box G Window Rock, AZ 86515

(602) 871-5851

P 735 5 % 6 % 2 5

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED

NOT FOR INTERNATIONAL MAIL

(See Reverse)

Sent to Raymond Barton

Street and No

Navajo Tribal Motor Pool

P.O. State and ZIP Code

Posting Pool

Restricted Delivery Fee

Special Delivery Fee

Restricted Delivery Fee

Restricted Delivery Fee

Special Delivery Fee

Restricted Delivery Fee

Restricted Delivery Fee

Special Delivery Fee

Special Delivery Fee

Restricted Delivery Fee

Restricted Delivery Fee

Special Delivery Fee

Special Delivery Fee

Special Delivery Fee

Restricted Delivery Fee

Restricted Delivery Fee

Special Delivery Fee

Special Delivery Fee

Restricted Delivery Fee

Special Delive

28et enul ,0085 mio 295