July 18, 2003

Site #2000-16783

Larry Pitts Pitts Indian Ave., Inc. Mr. Eric Roehl Chevron Products Co. P.O. Box 2292

490 S. Indian Avc. Palm Springs CA 92262

Brea CA 92822-1192

RE:

Underground Storage Tank Cleanup at South Indian Gas/Former Clayron Station #9-3670 at 490 South Indian Canyon Drive, Palm Springs

Dear Responsible Parties,

This letter confirms the completion of site investigation for the underground storage tanks located at the above described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the underground storage tanks are greatly appreciated.

Based on the information in the above-referenced file, and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation carried out at your underground storage tank site is in compliance with the requirements of subdivisions (a) and (b) of Section 25299.37 of the Health and Safety Code and that no further action related to the petroleum release at the site is required.

This notice is issued pursuant to subdivision (h) of Section 25299.37 of the Health and Safety Code. Please contact our office if you have any questions regarding this matter.

Sincerely.

Director of Environmental Health

Enclosure: Case Closure Summary

CC:

Abdi Haile, CRRWQCB

Cleanup Fund

Mike Kellner, Agua Caliente Band of Cahullia Indians

file

edos.br 03/26/97

CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK PROGRAM

SITE NAME: South Indian Gas

SITE NO: 2000-16783

Date: 6/6/03

I. Agency Information

AGENCY NAME: County of Riverside, Department of Environmental Health

Hazardous Materials Management Division

ADDRESS:

47923 Oasis Street, Indio CA 92201 (760) 863-8976

STAFF PERSON: Linda D. Shurlow, REHS-- Hazardous Materials Management Specialist

II. Case Information

SITE NAME: South Indian Gas

SITE ADDRESS: 490 S. Indian Ave. Palm Springs

RB LUSTIS CASE NO:

LOP/LOCAL CASE NO: 2000-16783

URR FILING DATE: 10/4/00 SWEEPS NO:

 RESPONSIBLE PARTIES
 ADDRESS
 PHONE NUMBER

 Pitts Indian Ave., Inc.
 115 S. Indian Ave. Palm Springs CA 92262

TANK#	SIZE	CONTENTS	REMOVED/CLOSED IN-PLACE?	DATE
1-3	10,000 gal	gasoline	removed removed	8/30/00
4	500 gal	waste oil		8/30/00

III. Release and Site Characterization Information

CAUSE & TYPE OF RELEASE: gasoline

SITE CHARACTERIZATION COMPLETE? Yes [X] No []

DATE APPROVED BY OVERSIGHT AGENCY: 6/6/03

MONITORING WELLS INSTALLED? Yes [] No [X] NUMBER:

PROPER SCREEN INTERVAL? Yes [] No [] N/A [X]

HIGHEST GW DEPTH BELOW GROUND SURFACE: 180'

LOWEST DEPTH:

FLOW DIRECTION: southeast

MOST SENSITIVE CURRENT GW USE: domestic

ARE DRINKING WATER WELLS AFFECTED? Yes[] No [X]

AQUIFER NAME:

SURFACE WATER AFFECTED? Yes [] No [X]

NEAREST/AFFECTED SW NAME:

OFF-SITE BENEFICIAL USE IMPACTS (ADDRESS/LOCATIONS):

REPORTS ON FILE? Yes [X] No []

LOCATION OF REPORTS: County of Riverside, Department of Environmental Health

Hazardous Materials Management Division

4065 County Circle Drive P.O. Box 7600 Riverside CA 92513-7600

(909) 358-5055

CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK PROGRAM

SITE NAME: South Indian Gas

SITE NO: 2000-16783

III. Release and Site Characterization Information (cont.)

TREATMENT & DISPOSAL OF AFFECTED MATERIAL							
MATERIAL	AMOUNT	ACTION (Treatment or disposal & destination)	DATE				
TANK PIPING RINSEATE SOIL GROUNDWATER OTHER	4	removed	8/2000				

MAXIMUM DOCUMENTED CONTAMINANT CONCENTRATIONS Before & After Cleanup							
	SOIL				GROUNDWATER		
CONTAMINANT	BEFORE	DEPTH	AFTER	DEPTH	BEFORE	AFTER	
TPH (GAS) TPH (DIESEL) TRPH (418.1) BENZENE TOLUENE XYLENE ETHYLBENZENE MTBE LEAD	52 ppm 12000 ppm 10 ppb 160 ppb 740 ppb 94 ppb 7.1 ppm 1.3 ppm	15' 5' 15' 15 15' 15' 15'					

COMMENTS (soil types, depth of remediation, etc.): sand with gravel and cobbles a 24 hour and a 5 day sve test completed.

IV. Closure

DOES COMPLETED CORRECTIVE ACTION PROTECT EXISTING BENEFICIAL USES AS PER THE REGIONAL BOARD BASIN PLAN? Yes [X] No [] DOES COMPLETED CORRECTIVE ACTION PROTECT POTENTIAL BENEFICIAL USES PER THE REGIONAL BOARD BASIN PLAN? Yes [X] No [] DOES THE CORRECTIVE ACTION PROTECT PUBLIC HEALTH FOR CURRENT LAND USE? Yes [X] No [] SITE MANAGEMENT REQUIREMENTS:
SHOULD CORRECTIVE ACTION BE REVIEWED IF LAND USE CHANGES? Yes [] No [X]
MONITORING WELLS DECOMMISSIONED? Yes [] No [] None Installed [X] NUMBER DECOMMISSIONED: NUMBER RETAINED:
LIST ENFORCEMENT ACTIONS TAKEN: LIST ENFORCEMENT ACTIONS RESCINDED:

CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK PROGRAM

SITE NAME: South Indian Gas

SITE NO:2000-16783

V. Local Agency Representative Data

NAME: Earl Tuntland SIGNATURE:

TITLE: Asst. Environmental Health Administrator

7/2MB3 DATE:

VI. **RWQCB Notification**

DATE SUBMITTED TO RWQCB: RWQCB STAFF NAME: Abdi Haile RWQCB RESPONSE:

TITLE: Senior Eng. Geologist

SIGNATURE: ()

DATE:

VII. Additional Comments, Data, Etc.

On August 30, 2000, three gasoline and one waste oil tank were removed from the site. Soil samples taken at 5 feet under the waste oil tank showed 12,000 ppm TRPH and 20 ppm at 9', 58 ppm at 12'. Soil samples under the dispensers were all ND for TPHg, BTEX and MTBE except for one MTBE hit of 26 ppb under dispenser 1. Soil samples from under the tanks showed a high of 52 ppm TPHq, 10 ppb benzene and 7.1 ppm MTBE. The site was placed into the LOP program.

Chevron Products Company took responsibility for the cleanup. On June 4, 2001, they drilled 4 borings on the property. The borings were proposed to be a minimum of 50' deep however cobbles in the subsurface caused auger refusal at 42.5', 32', 30', and 31' bgs. All samples were ND for TPHq, BTEX and MTBE with two exceptions. Boring 1 had MTBE hits of 22 ppb at 35' and 8.4 ppb at 42.5' bgs.

The consultant requested closure based on the results of the investigation and the depth to groundwater. The nearest public well is located % mile east of the site. Closure was denied and a 24 hour ve test was required.

On March 21 and 22, 2002, a high vacuum 24-hour vapor extraction pilot test was conducted at the site. TPHg levels decreased from 560 to 290 ppmy at the end of the test. Benzene increased slightly from 6.5 ppmv to 6.9 ppmv. MTBE was not detected. An estimated 49 pounds (7.7 gallons) of petroleum hydrocarbons were destroyed during the test.

The consultant again requested closure based on the results of the vapor test which showed hydrocarbon concentrations near the threshold Chevron uses for terminating the operation of a vapor extraction system. Closure was again denied due to the amount hydrocarbons removed during the test and a 5-day test was requested.

During May 1 through May 8, 2003 a 5.3 day sye test was completed at the site with a flow rate of 96 scfm and a vacuum of 20 ins water. The initial vapor sample showed 2.6 ppmv TPHg and no BTEX or MTBE. The ending sample showed no TPHg, BTEX or MTBE. An estimated 0.4 lbs (0.06 gallons) of hydrocarbons were removed during the test.

The consultant is again requesting closure based on previous and current investigations at the site.