



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street
San Francisco, CA 94105-3901

RECEIVED
APR 11 1995
NAVAJO ENVIRONMENTAL
PROTECTION ADMIN.

Norma

APR 3 - 1995

REFER TO MAILCODE H-W-4
and SITE # NAV- 158
Certified Mail Z 695 245 165

Ms. Joyce Daza
Vice President Operation
Navajo Communications Company
Window Rock, AZ 86515

Dear Ms. Daza:

This correspondence refers to the "Report for Soil Remediation at the Navajo Communications Company Facility" prepared by ERM- WEST, Inc. dated February 1995. The facility is located in St. Michael, AZ, on land of the Navajo Nation.

The soil remediation report describes the three phase excavation at the diesel dispenser area and the stained soil area. All contaminated soils were transported off site for treatment and disposal. Analytical results of samples taken in both areas confirm that all contaminated soils had been removed.

The information submitted has assisted EPA in assessing the status of this site. It does not appear to currently pose a threat to human health and the environment. **EPA does not require further action at this time.**

Sincerely,

Patricia D. Eklund, Chief
Office of Underground Storage Tanks

cc: Norma Cady, NEPA
Leonard Robbins, BIA
David Wyaco, Sr., BIA
Chuck Dowell, IHS

ATTACHMENT: LIST OF CONTACTS

Norma Cady, UST Program
Navajo EPA
P.O. Box 9000
Window Rock, AZ 86515 (602) 871-7691

Leonard Robbins
Bureau of Indian Affairs
Navajo Area Office
P.O. Box 1060, Code 305
Gallup, NM 87305 (505) 863-9501

David Wyaco, Sr.
Area Facility Manager
Bureau of Indian Affairs
Navajo Area Office
P. O. Box 1060
Gallup, NM 87305 (505) 863-8278

Chuck Dowell
Indian Health Services
Box G
Window Rock, AZ 86515 (602) 871-5851